

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Mitchell, Marsh & Ireton Ranch
Montour Vicinity
Gem County
Idaho

HABS No. ID-35

HABS
ID

23-MONT.V,
2C-

Barn

- | | |
|-----------|--|
| ID-35-C-1 | EXTERIOR, SOUTH AND EAST ELEVATIONS, LOOKING WEST-NORTHWEST
(Robert Ryan, Photographer, April 1979) |
| ID-35-C-2 | EXTERIOR, NORTH ELEVATION
(Hans Muessig, Photographer, April 1979) |
| ID-35-C-3 | EXTERIOR, WEST ELEVATION, LOOKING EAST-SOUTHEAST
(Robert Ryan, Photographer, April 1979) |
| ID-35-C-4 | EXTERIOR, SOUTH ELEVATION
(Robert Ryan, Photographer, April 1979) |
| ID-35-C-5 | EXTERIOR, EAST ELEVATION, DOORWAY
(Hans Muessig, Photographer, April 1979) |
| ID-35-C-6 | EXTERIOR, DOORWAY DETAIL, WEST ELEVATION, LOOKING NORTHEAST
(Sarah Dennett, Photographer, April 1979) |
| ID-35-C-7 | INTERIOR, LOOKING SOUTHEAST
(Hans Muessig, Photographer, June 1980) |
| ID-35-C-8 | INTERIOR, NORTH-SOUTH CENTER AISLE, LOOKING SOUTH FROM
NORTH END
(Hans Muessig, Photographer, June 1980) |
| ID-35-C-9 | INTERIOR, NORTH-SOUTH CENTER AISLE, LOOKING NORTH
FROM CENTER
(Hans Muessig, Photographer, June 1980) |

- ID-35-C-10 INTERIOR, EAST-WEST CENTER AISLE, LOOKING EAST FROM
WEST DOOR
(Hans Muessig, Photographer, June 1980)
- ID-35-C-11 INTERIOR, HORSE STALLS, LOOKING SOUTHEAST FROM NORTHWEST
CORNER OF BARN
(Hans Muessig, Photographer, June 1980)
- ID-35-C-12 INTERIOR, LOOKING SOUTH FROM CENTER
(Hans Muessig, Photographer, June 1980)
- ID-35-C-13 INTERIOR, LOOKING TOWARD SOUTHEAST CORNER
(Hans Muessig, Photographer, June 1980)
- ID-35-C-14 INTERIOR, COW STALLS, LOOKING SOUTH
(Hans Muessig, Photographer, June 1980)
- ID-35-C-15 INTERIOR, COW STALL, LOOKING SOUTHEAST
(Hans Muessig, Photographer, June 1980)
- ID-35-C-16 INTERIOR, COW STALL, LOOKING WEST
(Hans Muessig, Photographer, June 1980)
- IC-35-C-17 INTERIOR, LOFT AND ANIMAL PEN, LOOKING WEST
(Hans Muessig, Photographer, June 1980)
- ID-35-C-18 INTERIOR, TOP OF CENTER AISLE POST, LOOKING SOUTHWEST
(Hans Muessig, Photographer, June 1980)
- ID-35-C-19 INTERIOR, TOP OF SIDE AISLE POST, LOOKING SOUTHEAST
(Hans Muessig, Photographer, June 1980)
- ID-35-C-20 INTERIOR, WALL POST
(Hans Muessig, Photographer, June 1980)
- ID-35-C-21 INTERIOR, FOUNDATION, CENTER OF NORTH ELEVATION,
LOOKING NORTHEAST
(Hans Muessig, Photographer, June 1980)
- ID-35-C-22 INTERIOR, FLOOR JOISTS AND BEAMS
(Hans Muessig, Photographer, June 1980)

HABS
ID.

23-MONT.V
2C-